C-47, 083. H-42 has heard nothing.
1500 No Flying

FRIDAY AUG 31.

0740 Aerodrome O.K.
1055 O/C WATCH - 11 ARP's on A/C Capt Peterson
1230 On Lt. Carlile H/C Cap't Peterman
1432 Cap't Kenney cleared into Bovingdon tomorrow at 1400 hrs. for Briefing to Azores. a/c 676-S.
1810 Airdrome inspected - S

Saturday ~~Aug~~ September 1, 1945

0805 Inspected airdrome
0915 11 a/c (369) airborne to Y-17 - one to Gibraltar, one to R-25 - one to Istrella
0916 Lt Allen to take responsibility of calling towers to Sup. Ops. - C.I.T.O. by Lt. Hudgins
1215 On Lt Rosen off Lt Carlile.
1420 Civil Airdrome unsatisfactory - S.
1800-30 B26-144 arrived from 344 B.G. to Pick up Lt Robeson - could not be contacted & a/c left.

Sunday, Sept. 2 1945

0800 Schweinfurt run scheduled for 1415.
1230 A/T inspected - S.
1330 Off Station Gen Arpin
1415 Aerodrome O.K.
1830 Last a/c down

MONDAY SEPT 3.

0830 Aerodrome OK. Observed
1730 On Lt. Carlile off Lt. Arpin
2110 No Contact or Flak sighting until tomorrow

Tuesday Sept. 4.

0015 Maj. McKinney in B-17 925 landed from Y-17
0930 Airdrome - S R/W 36 STOD
0945 Bombay Flying Control instructed to hold all Capt a/c until after lunch
1130 Bombay asked to hold all a/c until 1400 hrs
1330 " " " clear all a/c

Wednesday Sept 5, 1945

0715 Col Upham delay R-25 a/c. Ceiling 200 Vis 1800 yds.
0730 Inspected airdrome - S
0810 Called dir. to ask them to hold a/c from