[illegible] F.C.O. finally gave up trying to get flare path laid, grabbed very pistol with rest of wild men and went out to intersection of main R/W and 30 and fired flares. Men at top of rt doing same. A/c landed on second try and F.C.O. ran like hell.

Suggestions.

1. Keep Doctors quiet when they come to tower
2. Try to get an order out so a/c can land unless we have some kind of flare path
3. Keep doctors quiet, especially when they have been drinking!!!!!!!!

2245 855-W landed.

2250 Auxiliary unit on, but unnecessary per station engineer

P.S. I could have written a beautiful report if he hadn't made it.

Aug 6, 1945 - Monday

0003 Main lighting on.

0320 848-O - Weather a/c off

0330 Casey Jones a/c delayed.

0810 Off duty Lt. Cable - on Lt. Blair

0830 Make routine inspection — man R/W & permit clear of obst. & barricade

OFF WATCH Lt. Blair ON Watch as Tower

1300 Rbw changed to 36 W16 N18

1310 Make routine inspection of gen. Drome area. In reply to above Entry of 2130 (Lt. Cable) it is suggested that when we still have a/c ash at night - when foul weather is anticipated by the weather wheels, that an Emergency Rbw flare path be laid.

400 Off Watch Capt Peterman, On Watch Lt Caplin

1300 Off duty Lt. Agee - on Lt. Blair

1310 Make routine inspection — man R/W & permit clear of obst. & barricade

2200 Casey Jones a/c [illegible]

2230 [illegible]

2310 Off Watch Lt Blair On Watch Capt

0930 HF/DF Now serviceable.
0900 Aerodrome O.K.
got aircraft 44 ops in — in Watch Sgt. Reeve
1400 Made routine inspection of gen. dump area. S.
1800 Off Watch Capt Peterman On Watch Captain
1910 Tempsford may send us Proposed a B-24 due to bad weather at base.
2005 Tempsford landed own a/c
2130 Last aircraft R.O.N.
1145 Casey Jones and WX a/c scrubbed

WEDNESDAY Aug 8

0800 Off Watch Captain On Watch Lt Carlile.
0935 P.513 357 + 170 airborne for Speke from A.81 landed here because of weather. Allconcerned notified. a/c refueled. Div. Dcase Speke
1215 Christchurch called. Raining hard - field flooded completed ops. - special a/c tomorrow morning at same time. Christchurch informs Bournemouth Aldhurst
1320 Wx dumped to 06 S.A. to N.E.
1430 Off duty Lt. Bolold - on Lt. Blaise
1250 Speak A/C Directions of 50 P-51's 357 170. Weather 1500 early - 1/2 a mile 500 overcast complete - remain on ground pending clear of A/F and surrounds
1750 B-17's #811 & 495 returned S.T.A. Cause weather was encountered enroute. Light was spot on V-17 Type (Hydrogen (R.C.N.)
1800 On Lt. Carlile Off Lt. Blaise
1945 A.A.C.S. Enroll called a/c 438 Pilot Lt Sims - Cap did not reach destination at Tortorella today. Called 1st Div. and F.C. ops. for overdue action. We have to take overdue action per Group Contacted Cap 1st Ingram of 19th Photo Recon. for further info. Possibility a/c landed at Malignane - A.T.C. base near Nice to drop passengers.
Div. Checking further and to call back.