MISSING AIR CREW REPORT

IMPORTANT: This report will be compiled in triplicate by each Army Air Forces organization within 48 hours of the time an aircraft is officially reported missing.

Group 306th Bomb (H); Squadron 368th Bomb (H); Detector XXX

SPECIFY: Point of Departure Thurleigh, England; Course As prescribed Intended Destination Berlin; Type of Mission heavy Bomb

3. WEATHER CONDITIONS AND VISIBILITY AT TIME OF CRASH OR WHEN LAST REPORTED:

Good at altitude, but 6/10 undercast

GIVE: (a)Date 29 Apr/44 Time 1225; and Location Near Hanover, Germany

of last known whereabouts of missing aircraft. (b) Specify whether (x) Last Sighted; () Last contacted by Radio; () Forced Down; () Seen to Crash; cr () Information not Available.

5. AIRCRAFT WAS LOST, OR IS BELIEVED TO HAVE EEEN LOST, AS A RESULT OF: (Check only one ()Enemy Aircraft; (X) Enemy Anti-Aircraft; () Other Circumstances as follows

6. AIRCRAFT: Type, Model and Series B-17-G ; A.A.F. Serial Number 42-31556

7. ENGINES: Type, Model and Series R-1820-97; A.A.F. Serial Number(A) 43-62054
(b) 43-61650 ;(c) 43-61082 ;(d) 43-61837

8. INSTALLED WEAPONS (Furnish below Make, Type and Serial Number)

(a) F-649365 ; (b) F-649369 ; (c) F-649373 ; (d) F-649386

(e) F-729674 ; (f) B-890450 ; (g) B-890457 ; (h) C-267856 THE PERSONS LISTED BELOW WERE REPORTED AS: (a) Battle Casualty x

or (b) the restriction of (b) the restriction of (c) the restriction

NUMBER OF PERSONS ABOARD AIRCRAFT; Crew 10 ; passengers 0 ; Total 10 (Stabting with pilot, furnish the fellowing particulars: If more than 10 persons were aboard aircraft, list similar particulars on separate sheet and attach original to this form).

Mame in Full Serial Crew Position (Last Name First Rank Number Pilot - Pilot 2nd Lt | 0-444564 5 % Intz, Warren S.V KIA 2. Pilot - Co-Pilot Johnson, Thomas W. 2nd, Lt. 1 0-815495 KIA 3. Navigator - Navigator 7 O'Neill. Edward P 2nd. Lt 0-699234

KIA 4. Bombardier - Nose Gunner 3 Knox, James L. 2nd Lt. 0-747024

KIA 6. Radio Opr - Radio Operator 8 Reed. Joe D. V S/Sgt 1014096249

Kin 8. Armorer-Gun - Ball Turret G. /O Ward. Roy Y. Set. 38450434

Eus 9. Aer. Eng - L. Waist Gunner 4 Lazek, Aleck A. Sgt. 6952052 K

Armorer-Gun - Tail Gunner 6 Lux Charles H. Set 16139193
1. IDENTIFY BELOW THOSE PERSONS WHO ARE BELIEVED TO HAVE LAST KNOWLEDGE OF AIR

CRAFT, AND CHECK APPROPRIATE COLUMN TO INDICATE BASIS FOR SAME.

Check Only One Column Contacted MAR Name in Full Serial Last By Saw Forced (Last Name First) Number Rank Radio Sighted Crash Buttorff, Richard D. 2d Lt. 0-753780

IF PERSONNEL ARE BELIEVED TO HAVE SURVIVED, ANSWER YES TO ONE OF THE FOLLOWING STATEMENTS: (a) Parachutes were used ; (b) Persons were seen walking away from scene of crash por constant consta

13. ATTACH AERIAL PHOTOGRAPH, MAP, CHART, ORSKETCH, SHOWING APPROXIMATE LOCATION WHERE AIRCRAFT WAS LAST SEEN.

14. ATTACH EYEWITHESS DESCRIPTION OF CRASH, FORCED LANDING, OR OTHER CIRCUMSTANCES
PERTAINING TO MISSING AIRCRAFT.

15. ATTACH A DESCRIPTION OF THE EXTENT OF SEARCH, AF ANY, AND GIVE NAME, RANK AND



HEADQUARTERS 305TH BOMBARDMENT CHOUP (H) Office of the Commanding Officer United States Forces

(G-A-12)

APO 557. 30 April, 1944.

SUBJECT: Eye-witness account of incidents pertaining to Aircraft No. 42-31556, missing action, 29 April, 1944.

TO: Commanding General, Hq, First Bombardment Division, APO 557.

1. According to 2nd Lt. Richard D. Buttorff, eye-witness and Pilot of an aircraft in the same formation, the following is an account of what occurred on 29 April, 1944, to Aircraft No. 42-31556:

"At approximately 1225 hours, near Magdeburg, Germany, Lt. Lutz was hit by flak. The cover of the whole right wing seemed to be stripped off, he peeled up over the lead, rolled over and went down straight enveloped in flames. No chates were observed."

For the Commanding Officer:

C. G. Duy, Jr. / Major, Air Corps

Adjutant.

