

- 0830 Off Watch Lt. Blaise On Watch Lt. Arpin
 0840 Aerodrome O.K.
 0850 SCS found on for returning Carey Jones & c
 1145 On duty. back off Lt. Arpin.
 1240 Inspected airbase - S
 1750 Cancelled B-26's clearance to Burtonwood
 by phone. % will pass in morning
 1800 Off Watch Lt. Carlisle On Watch Arpin
 1830 Runways Inspected.
 2230 Night Lighting Inspected - O.K.
 0833 Weather at 1000 ft.
 0840 Off Watch Lt. Arpin On Watch Lt. Carlisle.
 0900 Inspected airbase - WIP perimeter 365 area
 RWs + perimeter need policing.
 1130 RW changed to 12 S.E. to N.W.
 1230 Off duty Lt. Carlisle - on Lt. Blaise
 1400 Made airbase inspection - WIP perimeter 365 area
 Cost of airbase fine of about £20000
 1435 Called motor pool (OinC) about lax driving
 of trucks etc. on perimeter and general
 full area (No incident this morning) Told
 OinC of signs at each RW and asked
 drivers to be briefed accordingly. We were
 asked to submit any and all names
 that cause trouble to Capt. _____
 OinC motor pool.
 1440 Called Col. Keeling about let down
 heading of 245° on buncher. New teletype
 to be sent out changing heading.
 1830 On Lt. Carlisle off Lt. Blaise
 1940 RW changed to 14 N.E. to S.W.
 2205 Inspected airbase - S
 2300 Capt. returned ON duty closing down at midnight
 2301 All Carey Jones (including WX % scrubbed per Capt. Ops.
 Turner Jones etc.
 0800 Off duty Lt. Carlisle on Lt. Blaise
 0820 Made airbase inspection - RW 30 clear of obs.
 0830 S.S. Pimple clear of obs.
 1200 On Watch Arpin Off Watch Blaise
 1300 Aerodrome O.K.
 1800 Aerodrome Red Div. Notified.

1630 Off duty Lt. Arpin - on Capt. Peterson
2130 " " Capt. Peterson - on Lt. Arpin
2215 Casey Jones scrubbed

WEDNESDAY - 11 JULY 1945

2300 Off duty Lt. Blain - on Lt. Arpin
1200 Off Lt. Arpin on Lt. Carlele
1836 Inspected airframe - S
1730 Col. Keeling cleared B-26 - 237 on instrument
conditions to Stratford. Route C.F.R. the rest of
way to Lijiang
1830 Off Duty Lt. Carlele - On Duty Lt. Arpin
1900 Airframe O.K. Spt.
2115 All flying postponed - Casey Jones & WX s/c scrubbed.

Thursday - 12 July 1945

0815 On Lt. Carlele off Lt. Arpin
1000 Casey Jones scheduled this afternoon. Sgts. see
a/c. IAF^{and} and AF/DF informed, to recall all a/c
1100 P.O.F. Farmingdale called - 1 Lancaster to check out
SCS-51 this afternoon anytime up to 1630 hrs.
SCS-5 to be left on.

1235 Off duty Lt. Carlele - on Lt. Blain
1445 Made airframe inspection - remain the usual
load of ord. & serviceable.

1630 B-11 # 717 airborne to us from Wattisham
informed as he did not want to land here but
requested permission to continue on to Geofrey
Wood. A signal may come signaling
stop to us - disregard same.

Note Ships going to Christ Church will turn out of
control that a complete list of all passengers
his request was placed to us by J.P. Christ

1810 On Lt. Carlele off Lt. Blain
2345 P-38 Col. Hall R.O.W. Thurlock - clearance cancelled
the bridge
2335 Last a/c down

2337 Inspected airframe lighting - S. Have needs
cutting badly along the lighting

13 July 1945 FRIDAY

0316 WX A/c all