

July 11, 1944

0400 ops. breakfast

0500 attended briefing data follows.

B1W24 fort 6. A.T.F. 29.71 Last time T.O. 0900

SF 0740

spares.

^{skip}

TAXY 0755

367-042-18

369-396

T.O. 0805

368-619-

423-418

0620 Cycle Relay cleared through division

T.O. 0845 count Flixstowe 10000 ft. 0930

going out to $51^{\circ}40'N - 02^{\circ}00'E$ 20000 ft. ~~as in at~~

Flixstowe 6,000 ft. 16:30-1730- E.T.A. base 1730 to 1800

- 0640 Made necessary calls for ops. T.O. all to be
 stationed by 0740
- 0810 Last ops 9c off
- 0850 Work started on perimeter between dispersals
 39, 44 and N-S end of NW-SE R/W. A/C
 will have to taxi to the left. Equipment will
 be moved at night so as to permit A/C to
 taxi through this area.
- 0920 Work on perimeter changed to area adjacent to dispersals
 49 & 50.
- 1651 A/C 063 Flying Spar landed.
- 1130 18 A/C closed thru division for gunnery mission
 T.O. 1400
- | | | | |
|-----------------|------------|-------------|--------|
| Cross Coast Out | Kings Lynn | 1500 | 10,000 |
| " " In | Kings Lynn | 1640 | 10,000 |
| On Range | | 1530 - 1630 | |
| Bases 1700 | | | |
- 143 A/C 943 368-L aborted. Ops down & 40% notified
- 1230 ON DUTY Capt. BRADBURY.
- 1300 BRIEF Inspection of airfield. Perimeter
 under construction at head of N-S Runway.
- 1335 Gunnery mission will cross coast in at
 1700 instead of 1640 - via Kings Lynn.
- 1730 All ops a/c down. a/c 575 - Nular X landed
 at Knettishall. Low on gas
- 1915 Nular "X" 575 returned to base from
 Knettishall.
- 2030 Two PFF's from Chelveston. # ~~558~~⁵⁵⁷ Monsoon
 T. # St. Fife and 691 Monsoon V St. Wood.
 ETA. 2245.
- 2100 Perimeter is closed to taxiing between
 dispersal 49 and N-S runway.