

1230 ON duty - LT. BASS Off - Lt. BIA/BE
 1245 INSPECTED AIRFIELD - O.K.
 1500 New ETA 15:55
 1610 All mission a/c down except
 604 A landed at B-67. (from Div.)

1830 Off duty Lt. Bass - on Lt. Glaise
 MONDAY - 19 MARCH 1945

0545 Briefed 3000. #12 710 Alt 24.
 1000 High Low

SE	0700	0706	0712	FOX HOLE
Top	0815	0824	0837	ZAKER
7/6	0825	0831	0837	

0710 Forty five minutes (45) delay.
 New times:

	1000	High	Low	LTTO - 0955
SE	0845	0851	0857	E.T.R - 1455
Top	0900	0904	0912	Ref Alt - 23000
7/6	0910	0916	0922	Z-Hook - 0945

0900 Off duty Lt. Glaise - on Lt. Bass. W/HOOD - ATU

0835 INSPECTED RW - O.K.

0837 35 ac off. Nuhar made false start &
 ran off runway.

0952 NUHAR "K" off

1125 On duty Lt. Baskie off Lt. Bass.

1915 Inspected airrome. P/W's & Prim S.
 W.I.P. off perimeter on N-side of drome
 also in disp 50

1715 necessary calls made for opp. return
 all to be stationed by 1800 hrs. E.T.A. 1836

1830 ON duty - Lt. BASS Off - Lt. CARHART

1905 All mission a/c down except 287

1930 287 V down
 2300 Stood down.

20 MARCH '45

0800 On Lt. Baskie off Lt. Bass.

0830 Inspected airrome - S

1000 Flying this afternoon will in the following
 SBS-51 - 1330 to 1530 hrs. - Transition - 1530 - 1730
 S range. Sply formation. J.H. flying

1240 Off duty Lt. Baskie On Capt. Peterman

1330 Lt. Johnson's P/W's in air are diversion