

23 March 1944

0300

Ops. breakfast.

0400

Attended briefing: data as follows.

Start Engines; yellow yellow - 0650 367 - SQT O.C.S.

Taxi Red yellow 0700 368 - MRF

Take off Green Green 0715 369 - IRAQ

Scrubbed Red Red. 423 - WMQ

Standby Green yellow

Spares. 558, 827 and 172

Briefed QFE 30.00

Deadline 0800.

- 0540 Weather Ship. cleaned thru division
- 0545 Necessary calls for I.O. made.
- 0633 Masquerade as briefed per Noth C.W.
- 0700 Yellow to ops. & dir.
- 0835 Made routine inspection of airfield
- 0850 Gave standby weather report to D.F.
- 1110 Gave D.F. weather report for return of Ops.
- 1130 Made necessary calls for
return of ops
- 1215 on watch H. Fisher
- 1330 All our non. op. at home.
- 1420 Made routine inspection of general drone area.
- 1550 Dressed com "2 K" to crew.
- 1700 Blue path laid NE/SW-24.
- 2015 Made routine inspection of general drone area.
- 2030 148 "T" weathered in at Dunholme Lodge. Instruments
also 4/5 will return sometime tomorrow. All concerned notified