

0130 July 27, 1944

Briefed 39 crews:

S.E. 0422 LTTD 0550

TAXI 0437 Off 29.80

T.O. 0447 R/W 24

0230 Cleared weather ship 180-K thru division T.0315

0330 Relay ship cleared through division. 323 Nuclear M.

T.O. 0540 direct to Fulestone 8000 at 0630 to 5140'N-

0220'E 20000 until recalled back in at Fulestone 8000

0428 MISSION SCRUBBED RR FLARES FIRED

0730 On duty Lt. Carlile Off duty Lt. ~~Carlile~~ Sibley

0810 Chaud 367 K thru first div. to drop D.A. Bombs.

Coordinates for dropping are 5228'N 02045'E

0830 Construction on 06 RW and perimeter by 06

1750 Off duty Lt. Carlile

1750 On duty Lt. Sibley

1830 Inspected aerodrome. R/W 06 near perimeter will be ready by midnight

1835 Alerted

2150 Division notifies us to stand by from desk to dawn for 9th A.F.

2235 PFF 756 Lt. Fife Liftbay "N" w/IT SBN landed 2232

" Lt. B. Walker Liftbay "W" w/IT T.T. landed 2225

2250

Have puth on 24
y