

April 4, 1944

0630

Yellow to ops.

0840

Made routine inspection of airfield. Disp. 21  
underwater and various parts of perimeter track  
underwater.

0900

Red to ops.

0905

Station electrician notified of perimeter light  
failure

1000

SBA outer marker N/S - signal notified  
they are signalling it N/S to ops

1200

Capt. Bradbury on duty.

1250

outer marker now serviceable.

1250

Perimeter track now serviceable.

1255

airdrome yellow.

1345

On runway 24

1515

learned that H/F D/F transmitter at but is up  
but they can work from their main station.  
Div. inquired about this and we passed above  
to them.

1645

Ops notified us of stand down.

7 case rock on RW 24

1900

2008

SBA turned off until 0200 at request of

LITTLE, STAUGHTON &

Weathering Comms. - Division notified.

2016

HF ADVISES HF-DF NOW "S"

2030

Suspected general airdrome.