

2400 Lt. Graham suggested we assign a call sign to  
all the ships. I called Capt. Roebuck - Lt. ship,  
and continued to not sign call signs as it was not  
permitted to assign call signs without proper  
the channel. This may be taken care of when you  
is transferred to continent.

1800 On Lt. Bailie off Lt. Plaine

1805 Lt. Redwell called about four Altimeters supposed  
to be in tower. Following information given to us.

T.O. 05-30-1 Published 11 April 1943 Sec. 3A 1241

Revised 20 Nov. 1943

Sec. 8 A 3C - Station Altimeter Calibration

18:45 I inspected Airdrome - S

2130 Bombay called and they are sending B-26 #149  
Tonight from A-92 to pick up personnell  
for there and leave first thing in morning.  
E.T.D. after 2300 hrs. Attempted to contact  
leave center, no reply

2535 No B-26

2350 Called I.A.D. about above B-26 #149 from A-92  
they will check Bombay and call us back.

SATURDAY July 8, 1943

0045 Mr. Bridge called B-26 left A-92 at 2235 B.  
Div. has same information. Still no B-26

0140 Div. & T.C. ops Mr. Bridge informed of possible action  
on B-26-149.

0459 WX 3/4 off. - 676-5

0747 365-V #552 first Carry James off

0800 Off duty Lt. Bailie - on Lt. Plaine

0845 Capt. informed us B-26 # 149 landed at 2350 hrs  
last night. Informed Mr. Bridge & Lt. Div.

1010 Made airdrome inspection - main RW and perimeter  
clear of obs. and suitable.

1240 OFF DUTY - Lt. B. House ON DUTY - Capt. Peterman

1400 made routine inspection of gen. Drone area

1730 FIT mt.

1830 off duty Capt. Peterman - on Lt. Plaine

1900 Made airdrome inspection - acro.

0001 All quiet.  
Capt. Peterman is not on the fall.

July 8th

0135 Weather a/c off.

- 0735 Last Carey Jones off  
 0800 Off Watch Lt Blaise On Watch Lt Capin  
 0830 Airborne O.K.  
 1145 SCS Appear on for returning Carey Jones etc  
 1200 On H. baile off Lt Capin.  
 1240 Inspected airbase - S  
 1750 Cancelled B-26's clearance to Burtonwood  
 by phone. It will pass in morning  
 1800 Off Watch Lt Capin, On Watch Lt Blaise  
 1830 Runways Inspected.  
 2230 Night Lighting Inspected - O.K.  
 0333 Weather a/c off.  
 0540 Off Watch Lt Capin, On Watch Lt Blaise.  
 0900 Inspected airbase - WIP perimeter 366 area  
 NW & perimeter need policing.  
 1150 NW changed to 12 SE to N.W.  
 1220 Off duty Lt. Capin - on Lt. Blair  
 1400 Made airbase inspection - WIP perimeter 366 area  
 Best of airbase free of obstr. & serviceable  
 1435 Called motor pool (O in C) about lax driving  
 of trucks etc. on perimeter and general  
 full area (We incident this morning) Told  
 O in C of signs at each NW and asked  
 drivers be briefed accordingly. We were  
 asked to submit any and all names  
 that cause trouble to Capt. \_\_\_\_\_  
 O in C motor Pool.  
 1440 Called Col. Keeling about let down  
 heading of 245 on bencher. New teletype  
 to be sent out changing heading.  
 1830 On H. baile off Lt. Blaise.  
 1940 NW changed to 24 NE to S.W.  
 2205 Inspected airbase - S  
 2300 Capt. Pitman on H. closing down at midnight  
 2301 All Carey Jones (including WX % scrubbed per Sgt Ops.  
 Tuesday July 29 1958  
 0800 Off duty Lt. Capin on Lt. Blair  
 0830 Made airbase inspection - NW 30 class of obs.  
 0930 People class of obs. S. P.L.