

0800

Oct. 11th Monday
on watch d.d. Peterson

0805 "Red" to Ops. Dense ground fog - no activity anticipated
this A.M.

1220 On duty H. Taylor

1255 "Yellow" to Ops. Wind nil.

1415 Wind - W-N-W. 5 mph.

1425 Runway changed to 8 to 11. SW-NE

1430 Insp. air field - drip. Taxi lanes etc. O.K.

1600 "Green" to Ops.

1615 Comm. I-S. have been issued to beacon crew with
inst.

1740 On Watch - Lt. Peterman.

1825 Made routine inspection of Gen. Drone Area.

1843 "Yellow" to ops.

1845 Our Pundis requested from Deck to down? (w. 9k)

1900 Instructed flare path to be laid NE/SW.

1905 All air a/c down - flying ended for tonight
Crew & ambulance dismissed.