

Wednesday 15 Dec. 1943

- 0715 yellow to ops.
- 1000 make routine inspection of General Alrome Area. In order.
- 1100 15<sup>th</sup> Dir. I/C inform us it is ok to let P.F.G. A/C return to Alconbury - this afternoon - but before doing so make final weather check with 15<sup>th</sup> Dir. & A/C company.
- 1230 On duty - Lt. Heck.
- 1504 Permission to return to Alconbury denied Chapstick "G"  
all concerned notified - guard placed - crew returns to base
- 1700 Flare path laid R/W 06 - SW-NE.