

15 JUNE 1944

0030 Ops. Breakfast

0145 Briefing & data follows

SPW24 Wind WNW 13 Briefed GTF 30.03

SE 0427 YY 0436 O/S Spans

TAXY 0442 RY 0451 367 - 729

T.O. 0452 GG 0501 368 - 946

Scrub. RR 369 - 196

Delay GY 423 - 180

- 0250 Heard weather ship thru division
- 0255 Intruder broadcast.
- 0338 Weather ship airborne
- 0330 Made necessary calls for ops. T.O.
- 0324 No change in masquerade per 40 C. B. W.
- 0815 Lt. Crowell on
- 0830 Clerk of works still on disp 41 today
- 1045 Caravan wrecked by 367-D landing with two engines
- No one hurt.
- 1100 Weiland called - Down at Chilbolton - crew O.K. # 304 engine
out - hit primary.
- 1145 Div. informed of two a/c on runway 24
- 1230 On duty Capt. BRADBURY
- 1315 Inspected airframe. Tarmacing still in
progress on NE end main R/W.
- 1710 Changed R/W to 24 -
- 2100 We are alerted.
- 2115 Standby for 9th A.F. bombers.
- 2200 Alert crew chief at EXT. 90
- 2325 Mission scrubbed.