

15 Sept 1943

0830 Wind West - 12 mph

0910 Briefing 1300 hrs.

0830 Inspected airdrome and noted defective
spot on main runway - and totter pole
on ~~at~~ main runway NE end is knocked out
of line.

1820	Our permit requires dest to down.
1830	attended Briefing. R/W NF-SIN.
	Start Engines 1510 Start Engs - Cocktail
	Taxi 1520 Stand by - Turkey
	Tone off. 1530 Delayed - Icecream
	E.T.A. 2028 Scrubbed - Fingerbowl
1400	Avionics inspected. make arrangements for Antennas, Cross tanks, M.p. Citrus.
1930	Inspected avionics. briefed XC8 crew make arrangements for Antennas, cross tanks, M.p. & citrus.
2125	Informal at 1000 O load at Birmingham at 2119.
2210	and informs us. wind ESW - 22 mph.
2220	Air raid surge
2221	Air raid rd.
2240	air raid writes.
2250	Wiper Seizing Completed.