

17 April 1944

- 0700 Field red to ops & div.
- 0830 Engineers will be repairing perimeter where it intersects runway 36. a/c will be able to get through. It will take about three days
- 1045 alerted for ops
- 1130 Briefing for ops mission at 1300.
- 1200 Field yellow ops & division.
- 1230 On duty Lt. Callile
- 1300 Attended Briefing Data follows:
Start Eng. 1524 YY O.K.S.
taxi 1539 RY
T.O. 1549 GG
Scrubbed RR
delayed GY
Briefed Q.P.F. 30.00
Pilots briefed on position of pundit.
- 1405 Made necessary calls for ops. T.O. to be in position at 1520
- 1415 I instructed pundit crew that they must be flashing by 1930 hrs.
- 1515 Masquerade same - per 40th C.W.
- 1525 Mission scrubbed - Red Red fired
- 1605 Made routine inspection of general drone area
- 1630 7 lane path to be laid on P/W 06
- 2110 Made routine routine inspection of airfield sign
- 2200 We are alerted