

FRIDAY FEBRUARY 18, 1944

- 0730 YELLOW, PASSED to 1st Div & LTRP OPS
- 0840 made routine inspection of gen. drone area.
- 1112 Drone Red - ops & Dir notified
- 1300 Alconbury advise us to keep Transit A/c #561 here until tomorrow - Their field ind. Crews of A/c & Hitting informed of above.
- 1310 "yellow" to ops.
- 1312 Ops. advise us small number of a/c will S/T this PM. Met. OK's flights - Crews instructed to stay within sight of field and below cloud. Keeping level 1000!
- 1609 Drone - Green - ops advised.
- 1650 Place patch to be laid on R/W of
- 1820 Stand down for tomorrow.
- 1825 1st Div. asked if we could accept two stirlings tonight. Checked with met weather fair told division that weather would hold up until 2200.
- 1830 1st division says no stirlings tonight.
- 1840 Made routine inspection of drone
- 1845 1st Division requested we call "Car Smash Q" and fire every kind of flare we have. To belong to Station Plots were passed on the "Q" to us and we continued to fire flares Rockets etc.
- 1850 Made contact with Car Smash "Q"
- 1900 Car Smash "Q" B-47 # 478 landed division says "Q" to remain until further instructions received here
- 1905 Station called they are sending transportation for ~~the~~ Car SMASH "Q"