

Aug 29, 1944

0021

All A/C down except 087.

0040. Pilots reported outer circle west of field is U/S

AUG. 29, 1944 - TUESDAY

0055 A/C 087 landed.

0700 Given to ops & division

1215 On duty Lt. Carlile

1270 Inspected airfield - Tarmacing on perimeter track at N.E. end of main R/W. Contact lighting broken out by new tarmacing on main R/W. (4 lights broken out on cross bar at start of above R/W. Contacting electrician about it.

1330 R/W changed to 18 S to N

1340 OFF for tomorrow 29.85

1850 No night flying and we are stood down.

2030 R/W changed to 24 N.E. to S.W. for night

2220 Inspected airfield lighting. R/W 24 has about half of drum system out or covered up on left side. Perimeter lights O.K. except for a few that are burned out.