

Sunday 29 October 1944

07:15 Red to division & ops.

0800 On duty Lt. Cartile off duty Lt. Klein

0820 I inspected airfield - 423rd area and 423rd cat off still closed.

R/W changed to 06 SSW NE

0905 Call Capt. Cubberly about fence down at 30 R/W asked him to make some repairs as cows are coming out on field. Mrs. Gillum's office could not be contacted.

0940 Capt. Niblack (3d. ops.) informs us of night flying lecture today 1400 hrs. at 367th combat zone.

1253 Yellow to Div. and ops.

1300 I inspected airfield. Same as above.

Debris still along R/W 30.

1305 Lecture at 1400 scrubbed.

1400 Green to div. & ops.

1510 R/W changed to 12
1600 Twinwood airfield informs us that after tomorrow they will not have anything but 100 octane fuel for aircraft

Note {

1610 Col. Salada requests we turn in our
B-9 jackets and that we may draw
battle flying jackets. If possible we
may draw jackets for all of personnel.

1755 R/w back to 06

1800 On duty Lt. Sibley. Night flying has been
scrubbed. Crash Crew, Ambulances & D.C.P. dismissed

1815 Alerted.

1900 Inspected obstruction lights. Refusal 40 was unlighted.
Flare Path instructed to put green lamps there. R/W 36
U/S parked A/C. 30 & 24 acc 5. 423rd Adm & cut off all
steel U/S. Flare path on 06 - serviceable except one
light on bar 800' yds from end of R/W.

1915 Beacon checked in.