

1775 Division directed us to take over the mission

C-47, 083. H-42 has heard nothing.

1800 No Flying

FRIDAY Aug 31.

0730 Airframe O.K.

1055 OFF WATCH - Lt. ARPIN - ON WATCH Capt. Peterson

1230 On Lt. Carlisle off Capt. Peterson

1430 Capt. ~~Harvey~~ ^{Harvey} landed into Bowditch tomorrow at 1700 hrs. for briefing to Agos. a/c 676-S.

1810 Airframe inspected - S

Saturday ~~Aug~~ September 1, 1945

0805 Inspected airframe

0915 11 a/c ⁽³⁴⁰⁾ airframe to Y-17 - one to Sikatan, one to R-25 - one to Tortuga

0916 No one to take responsibility of calling times to Sup. Ops. - O.K'd by Lt. Stubbs

1215 On Lt. Rozen off Lt. Carlisle.

1420 Gen'l Airframe ~~was~~ inspected - S.

1800-30 B26-144 arrived from 344 B.G. to pick up Lt. Roberson - could not be contacted & a/c left.

Sunday, Sept. 2 1945

0870 Schweinfurt run scheduled for 1415.

1230 A/c inspected - S.

1330 Off watch on Arpin

1715 Airframe O.K.

1830 Last a/c down

MONDAY Sept 3.

0830 Airframe O.K. Ob in use!

1730 On Lt. Carlisle off Lt. Arpin

2110 No contact or flash lighting until tomorrow

Tuesday Sept. 4.

0015 Maj. McKinney in B-17 904 landed from Y-17

0930 Airframe - S. R/W to 36 STO N

0945 Bombay Flying Contest instructed to hold all a/c until after lunch

1130 Bombay asked to hold all a/c until 1700 hrs

1330 " " scrub all a/c

Wednesday Sept 5, 1945

0715 Col. Latham delay R-25 a/c. Calling 300 Vis 1800 yds.

0730 Inspected airframe - S

0810 Called dir to ask them to hold a/c until